

10 15 20 25 27 30 35 40 45 6

Quality Ticket

Serial Number: M00000002 Lookup Module Info Application Revision: 501

Ticket: 420 Get info Part Number Description

Close Quality Ticket

Symptom

Initiated By: Process Step (Test): OETI Initialize Module 75

Process (Test Stage): OETI Test Symptom 85

Symptom Category: N/A

Comment: Test no

Quality Ticket Explorer Save Cancel/New Defect No Defect Close

Area of Operation: 1 Client Operator: CENAVmmgaria, CENAVmmgaria 110 115 120 130 135

140 95

Figure 9

140

70

80

90

50

75

85

7a

200

280

210

290

385

300

285

220

315

310

320

335

360

350

Defect/Action Information for Quality Ticket: Ticket#: 4895 [SN: M0000001; PN: 130-0466-900; Rev: 001]

Operator: CIENA\dms\stuser1

Area of Operation: 10G

Process (Test Stage): OT1 - P1x

Process Step (Test): RX grating test

Symptom Category: I N/A

Symptom: N/A

Comment:

Defect:

Defect Category:

Components:

Comment:

Defect:

Defect Category:

Components:

Comment:

Defect:

Defect Category:

Components:

Comment:

Troubleshooting Guide

Save

To get the detailed information on each defect double click on the corresponding row or click on the Feedback button

Status	Defect Category	Defect	Reference Designator(s)
Not Fixed	Component Defects	Damaged	YERE, EEE
No Action	Component Defects	Damaged	tmdd
No Action	Component Defects	Damaged	GGG, DFDD, DDD
No Action	Component Defects	Damaged	

Feedback

Close

7

System Test

CIENA\dms\stuser1

Figure 10b